


# 2-Piece Power Cable Connection Diagram Air-Cooled TIG Torch

Air-cooled



**!** Turn off power before connecting to weld output terminal.