


Power Cable Adapter Connection Diagram

Water-Cooled TIG Torch

Water-cooled



! Turn off power before connecting to weld output terminal.